


Storage bracket

For up to 5 glove testing devices

Storage of one 5-fold charging station




Transport- and storage trolley

Storage of up to 10 devices

Storage of two 5-fold charging stations

Drawer for accessories

Central power supply



Glove port

In different sizes and shapes

For 8 - 20 mm glass

Incl. gasket and glove safety ring


Incl. RFID chip



Air filling gun


For glove filling






Single charging station

Charging of MK system battery packs



5-fold charging station

Charging of up to 5 MK system battery packs



MK system battery pack (small)

For MK test devices



MK system battery pack

For MK test devices

